

BINDOON HILL**ELEV 925****FULL NOTAM SERVICE NOT AVBL**

WA

UTC +8

YBHL

312025S

1161118E

VAR 1 DEG W

UNCR

AD OPR Superlight Aircraft Club of WA, PO Box 293, Bindoon, WA, 6502. Email: secretary@slacwa.org.au. PH AD MGR 0492 930 303.

REMARKS

1. PPR.
2. Previously known as Bindoon Abandoned.
3. See SLACWA Standard Operating Procedures at www.slacwa.org.au.
4. AD located within R155B.

HANDLING SERVICES AND FACILITIES

Nil fuel AVBL.

PHYSICAL CHARACTERISTICS

09/27 46a/c Bitumen and gravel. RWY LEN 1,400M. 900M WID 40
FM RWY 09 THR bitumen.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE 120.3

FLIGHT PROCEDURES

Right hand circuits RWY 27, avoid overflying houses on south side of Dewars Pool Rd, permission RQ before use.

CTAF 126.7**ADDITIONAL INFORMATION**

1. Recreational aircraft club, ultralights, motor gliders, homebuilts, vintage, gyroplanes, helicopters, trikes and powered parachutes.
2. Further information contact ARO.
3. AD is published on Perth VNC

CHARTS RELATED TO THE AERODROME

WAC 3462.