

WINDARLING**ELEV 1502****AVFAX CODE 6119**

WA

UTC +8

YWDG

300155S


1192314E

VAR 0 DEG E

CERT

AD OPR Yilgarn Iron Pty Ltd, 20 Walters Dr, Osborne Park, WA, 6017. Email:

windarling.aerodrome@mrl.com.au. ARO 0419 326 117, if not AVBL PH AD manager 0417 451 395.

**REMARKS**

Restricted OPS: PPR.

APRONS AND TAXIWAYS

TWY A: sealed, WID 15M.

AERODROME OBSTACLES

Vegetation 3FT AGL PSN 50M north of RWY CL for the entire length of RWY 10/28 infringes transitional SFC.

PHYSICAL CHARACTERISTICS

10/28 103 61a PCN 8 /F /A /522 (76PSI) /T Sealed

WID 30 RWS 90

AERODROME AND APPROACH LIGHTING

RWY 10/28 PTBL(1)

BY PRIOR
ARRANGEMENT

(1) EMERG only. 90MIN PN to ARO.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE

123.4 Circuit area.

LOCAL TRAFFIC REGULATIONS

1. From the TWY holding point, ACFT at THR RWY 28 may not be visible.
2. ACFT at THR RWY 10 and 28 may not be visible to each other.
3. ACFT ABV 5,700KG must complete LDG roll to RWY THR and use turn pads at each end of the RWY on ARR and DEP.

CTAF - AFRU 126.7**CHARTS RELATED TO THE AERODROME**

1. WAC 3351.
2. Also refer to AIP Departure and Approach Procedures.