NORTHAM FLEV 500

FULL NOTAM SERVICE NOT AVBL



WA 313733S 1164104E

VAR 1 DEG W

YNTM

AD OPR Northam Aero Club, PO Box 247, Northam, WA, 6401. Email: webmaster@northamaeroclub.com. PH 0428 880 149. Website:

www.northamaeroclub.com.

REMARKS

Latest info AVBL FM website or CTC AD OPR or 0407 873 700.

HANDLING SERVICES AND FACILITIES

AIR BP: Dunnings Fuel. MON-FRI Phone 08 9622 1413, AH 0438 035 328.

PASSENGER FACILITIES

WC

AERODROME OBSTACLES

Beware of power lines on the Great Eastern Highway Bypass.

PHYSICAL CHARACTERISTICS

14/32 41a Unrated. Sealed. RWY LEN 1,248M. RWY 14 WID 15 RWS 90

DTHR 175M. RWY 32 DTHR 98M.

AERODROME AND APPROACH LIGHTING

RWY 14/32 LIRL AFRU+PAL 124.2

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE 120.3 Circuit Area

LOCAL TRAFFIC REGULATIONS

- 1. Curfew for repetitive circuit training is 1300 UTC (2100 Local).
- 2. PRKG in front of Aero Club hangar reserved for fire fighting ACFT.
- Carriage and use of radio is required by the AD OPR.

FLIGHT PROCEDURES

RWY 32 - Right hand circuits.

CTAF - AFRU 124.2

ADDITIONAL INFORMATION

- Caution: Ultralight flight training.
- Turbulence near RWY 14 THR strong easterly wind.

CHARTS RELATED TO THE AERODROME

WAC 3351, 3462.