ELEV 1150

PENFIELD

VIC

373048S

UTC +10

YPFF

UNCR

FULL NOTAM SERVICE NOT AVBL

VAR 11 DEG E AD OPR Penfield Enterprises Ptv Ltd. 295 Settlement Road. Sunburv. VIC. 3429. PH AD Owners 0418 373 246: AD OPS MGR 0417 381 551.

REMARKS

- 1. Private airfield. PPR CTC owner or manager 0418 373 246 or 0417 381 551.
- 2. Radio is mandatory.
- 3. After several days of heavy rain, contact AD MGR for RWY condition.
- Twin engine ACFT by approval of OPS MGR. 4.
- Landing and overnight PRKG fees apply all ACFT. 5.

1444154F

HANDLING SERVICES AND FACILITIES

Nil fuel AVBL

PASSENGER FACILITIES

WC.

AERODROME OBSTACLES

- 1. Pine trees in TKOF splay RWY 36 and on APCH to RWY 18.
- 2. Concrete traffic bollards across the end of RWY 18. at the end of the over run area.

PHYSICAL CHARACTERISTICS

15/33	250	Unrated, Grass, RWY LEN 750M.	WID 30	BWS 45
10/00	200	officied. Glass. HWT LEIN 750M.	WID 30	1100 45
19/26	100	Uprotod Croop DWV LEN 1 020M	WID 20	DIMC 1E

18/36	40c	Unrated. Grass. RWY LEN 1,230M.	WID 30	RWS 45

ATS AND AERODROME COMMUNICATION FACILITIES 135.7 On Ground

FIA MELBOURNE CENTRE

LOCAL TRAFFIC REGULATIONS

- TKOF from RWY ends (noise abatement) except for TGL. 1.
- 2. Precautionary search training not permitted. Noise abatement.
- 3. All ACFT must park facing W on flight line. Entry is E of flight line and egress W of flight line.
- 4. Overnight PRKG AVBL.

FLIGHT PROCEDURES

- All CCTS to the W at 2.000FT AMSL and W of Riddell Road. 1
- Ultra-light ACFT (MAX 55KTS) CCTS to the W but E of Riddell Road. 2.
- 3. Do not overfly pine forest W of RWY intersection below 1,700FT AMSL. Paintball may be in progress.
- 4. Straight in approaches or base joins not permitted.

CTAF 121.6

ADDITIONAL INFORMATION

- Airfield used for ab Initio training. Students may be operating in solo CCTS. 1.
- 2. CAUTION: Note close proximity of CTA (S. E and above 2.500FT AMSL also Riddell Creek Airport 2.2NM N with CCTS to E.

CHARTS RELATED TO THE AERODROME

WAC 3469. 3470.