

HAMILTON ISLAND

RWY	(CN)	TORA	TODA	ASDA	LDA
14	(3)	1766 (5794)	1841 (6040) (1.69%)	1766 (5794)	1706 (5597)

Transient yacht masts may infringe RWY 14 APCH SFC clearance - Caution RQ.
 TKOF run commences at end of turning node.

32	(3)	1766 (5794)	1826 (5991) (2.02%)	1766 (5794)	1706 (5597)
----	-----	-------------	---------------------	-------------	-------------

1. OBST fence 7FT AGL located up to 76M from RCL SW side for first 500M from RWY 32 SOT. Infringes 14.3% TNS by up to 2FT.
2. RWS WID 90(295) for ACFT BLW 22,700KG MTOW by day in VMC. Marked by white cones.
3. TKOF run commences at end of turning node.
 Slope Level. RWY WID 45 RWS WID 150

SUPPLEMENTARY TAKEOFF DISTANCES

RWY14-	1786(5860)(1.6)	
RWY32-	899(2949)(1.6)	1609(5279)(1.9)